

## X/Y table engraver new mirror 1 notice

Since the new mirror is circle and easier to produce and maintain, GCC has changed the mirror 1.


The change starts from machine serial number [M95211](#).

The changed models: [SI](#)、[GE](#)、[SLS](#)、[GLS](#)、[GX](#)、[MIII](#)、[H230](#)


The changed laser tube wattages: [20V93](#)、[V30](#)、[30Vi](#)、[V40](#)、[T60](#)、[Ti60](#)、[60Ti93](#)、[80Ti93](#)、[80Ti](#)、[100T](#)、[100Ti](#)、[100Ti93](#)

**So for machine serial number older than M95211 (or invoice day earlier than August 01, 2013) and customer need to order mirror 1 for replacement, distributors also need to order new mirror 1 bracket for first time.**


The old and new mirror 1 can put on new mirror 1 bracket, but new mirror 1 cannot put on old mirror 1 bracket.




The old mirror 1 part number: [29003695G](#)



The new mirror 1 part number: [290077670G](#)



The old mirror 1 bracket part number: [20200185G](#)



The new mirror 1 bracket part number: [202003240G](#)